

NON STANDARD CONDITIONS			
NO.	ITEM	DESCRIPTION	DISPOSITION
	ROFA	SOUTHEAST SIDE RESIDENCES	NONE - MODIFICATION TO STANDARDS
2	ROFA	GLIDER PARKING	RELOCATE OUTSIDE ROFA
3	TAXILANE OFA APRON	TAXILANE CLEARANCES TO PARKED AIRCRAFT / FUELING (ADG I & ADG II)	RECONFIGURE APRON
4	PARALLEL TAXIWAY SEPARATION	LESS THAN STD. ADG II RUNWAY SEPARATION	RELOCATE
5	TAXILANE OFA (HANGARS)	LESS THAN STD. ADG I CLEARANCES	MODIFY WHERE FEASIBLE